


Fix for stuck tilt lock lever



cut along axis of tilt tube

cut in this region

I used a dremmel with cutoff wheel

It did not come out pretty or very straight but it worked

A utility knife might do a better job



cut here along axis of tilt tube